


寸法表

桁数	2桁	3桁	4桁	5桁	6桁	7桁
A寸法	101	151	201			
B寸法	96	146	196			
C寸法	50	100	150			
入力コネクタ	57-40240[DDK] (本体側)	57-40360[DDK] (本体側)	57-40500[DDK] (本体側)			
	57-30240[DDK] (ケーブル側)	57-30360[DDK] (ケーブル側)	57-30500[DDK] (ケーブル側)			



(注) 3桁ユニットは△印の金具位置には取り付けできません。